

Date: October 2017

Solenoid Test Manifold Kit

Now available from Drivetech, Solenoid Test Manifold Kit by Sonnax to suit Ford 6R60,75,80 - ZF 6HP19, 21, 26, 28, 32, 24 transmissions.

Fault:

The leading cause of solenoid failure in Ford 6R60, 6R75, 6R80, ZF 6HP19/26/32 (Gen I) and ZF 6HP21/28/34 (Gen II) units is an inability to maintain an internal mechanical seal, resulting in a multitude of drivability concerns.

Since it is not an electrical failure, it can be difficult to evaluate whether a solenoid is the cause of a particular problem.

Solution:

Sonnax solenoid test manifold kit 95430-VTK allows quick, easy pass/fail verification of the solenoid's internal sealing integrity, taking the guess work out of replacing solenoids.

- Must be used with Sonnax Vacuum Test Stand VACTEST-01K
- Test solenoid sealing reliability with vacuum by inserting solenoid snout into Sonnax test manifold
- **95430-VTK:** Solenoid Test Manifold Kit
- **VACTEST-01K:** Vacuum Test Stand

sonnax[®]



Part Number: 95430-VTK

Information on this sheet is prepared as a customer aid, from reliable information, with the utmost care and should not be used for any other purpose. Motospecs reserves the right to make product or publication changes at any time without notice.
© Copyright Motospecs, all rights reserved.

Australia
Ph: 1800 463 646
www.drivetech.com.au



New Zealand
Ph: 0800 333 125
www.drivetech.org.nz