

Overdrive Planet Pinion Washer Kits

Now available from Drivetech, Overdrive Planet Pinion Washer Kits to suit Ford 5R55N, S, W transmissions.

Fault:

Overdrive planetary pinion washers wear out resulting in excessive pinion clearance. This can cause planetary failure, if not rectified.

Solution:

Reduce out of pocket expense by replacing these affordable thrust washers instead of replacing the whole overdrive planetary when the planet is still serviceable.

Specifications:

- 6 Piece Kit
- Material: Bronze
- Thickness: 0.020"

46580A-W: Suits 38 tooth sun gear with 14mm diameter pinion pins

46580-W: Suits 24 tooth sun gear with 11.5mm diameter pinion pins

sonnax®



Part Number: 46580A-W



Part Number: 46580-W



Part Number: FX-36581A

Information on this sheet is prepared as a customer aid, from reliable information, with the utmost care and should not be used for any other purpose. Motospecs reserves the right to make product or publication changes at any time without notice.

© Copyright Motospecs, all rights reserved.